

## **BOOT NORMS**

O Warning:		Alpine Boots WTR/WTR+ Boots Grip Walk Boots Touring Boots Non-Compliant				
Any boot and binding combination, even if identified as compatible in this chart, must be installed, adjusted, tested, and regularly maintained by an authorized Salomon, Atomic or Armada dealer.		ISO 5355 certified alpine boots	ISO 9523 compliant WTR/WTR+ boots*	ISO 9523 compliant Grip Walk boots	ISO 9523 compliant touring boots	Touring boots not compliant with ISO 9523
BINDINGS			*WTR+ boots have Low Tech inserts			$\bigcirc  $ $\bigcirc $
<b>Alpine Bindings</b>		CA	•	<b>^</b>		•
500 9462	<b>Concerned Bindings:</b> All Salomon, Atomic and Armada alpine bindings without any logo indication	Compatible ISO 9462 bindings are intended for use with ISO 5355 boots	Not Compatible	Not Compatible	Not Compatible	Not Compatible
WTR Bindings	Bindings Stamped With	Ø	Ø		0	0
SUD ISO 9462 ISO 13992	STH <sup>2</sup> WTR, Guardian WTR, and Tracker WTR	<b>Compatible</b> ISO 9462 bindings are intended for use with ISO 5355 boots	<b>Compatible</b> WTR marked bindings are designed to work with WTR marked boots	Compatible WTR marked bindings are designed to work with Grip Walk marked boots with adjustment	Not Compatible	Not Compatible
Grip Walk Bindin	gs Bindings Stamped With	Ø	0		0	0
SUD ISO 9462 ISO 13992	Binding Systems: X14 TL GW, X12 TL GW, Z12 GW, FT12 GW, Z11 GW, FT11 GW, Z10 GW, L10 GW, FT10 GW, L6 GW Juniortrak, and C5 GW Juniortrak	<b>Compatible</b> ISO 9462 bindings are intended for use with ISO 5355 boots	Not Compatible	<b>Compatible</b> Grip Walk marked bindings are designed to work with Grip Walk marked boots**	Not Compatible	Not Compatible
<b>MNC Bindings</b>	Bindings Stamped With	Ø	Ø	Ø	Ø	0
SUD SUD ISO 9462 ISO 13992	Warden MNC (13 & 11), Warden MNC (13 & 11) Demo, Shift MNC 13, Guardian MNC, and Tracker MNC	<b>Compatible</b> ISO 9462 bindings are intended for use with ISO 5355 boots	<b>Compatible</b> MNC marked bindings are designed to work with WTR marked boots	<b>Compatible</b> MNC marked bindings are designed to work with ISO 9523 compliant boots	<b>Compatible</b> MNC marked bindings are designed to work with ISO 9523 compliant boots	Not Compatible
Atomic and Salomon Bindings With Pins		0				
Non-Certified	<b>Concerned Bindings:</b> MTN and Backland Tour	Not Compatible	Partially Compatible Bindings with pins require boots with compatible inserts. Consult an authorized dealer.	Partially Compatible Bindings with pins require boots with compatible inserts. Consult an authorized dealer.	Partially Compatible Bindings with pins require boots with compatible inserts. Consult an authorized dealer.	Partially Compatible Bindings with pins require boots with compatible inserts. Consult an authorized dealer.

This chart is intended as a summary of boot compatibility with current Salomon, Atomic and Armada bindings. Other factors, including product wear and damage, must be considered. Release value selection and adjustment and Boot-to-Binding adjustments such as forward pressure, toe width and toe height, must be made by a certified Salomon,

Atomic or Armada technician. \*\*Salomon, Atomic and Armada Grip Walk bindings are not meant to be used with boots that have metal inserts. Junior Grip Walk bindings (C5 GW and L6 GW) also support non-ISO norm Grip Walk Junior marked boot soles